THE TELOS ALLIANCE®
Create. Communicate. Connect.

Firmware Package 5.59 Installation Instructions for Axia iQ, Radius, RAQ & DESQ Consoles

3 October 2016, Cleveland, Ohio USA

Changes in this release

- OLED Brightness redefinition for value 0

Installation of New Software

Download the file **1661-00002-010(iq_firmware_group_file).bin** from the iQ, Radius, RAQ or DESQ product page at www.TelosAlliance.com/Axia and save it to your PC in a convenient location. Access the QOR control center from a browser by entering the IP address.

Select the *Module Information* link (#1)

At the bottom of the Modules page, locate the *Upload Firmware* and select *Choose File* button (#2) and locate the file previously downloaded. With the correct file selected, press the *Upload* button (#3).

The firmware group file is loaded and each module provides a drop down (#4) to select the new firmware. Select the new firmware and press the *Update* button (#5) to load the firmware. The module will stop operations as it loads and starts the new firmware. Repeat steps items #4 and #5 for each module listed.

Firmware v5.59 Release Notes

V5.59

- Brightness value of 0 will set the display into OFF state.

V5.56

- Added support for new serial ROM due to EOL issues.

V5.52

- Brightness test of overbridge added. Third meter controls brightness in test-mode.

V5.50

- Self test mode improvements.